




5/8" DIA
HOLE

1 SQUARE = 1"

A

C



TURNING LAYOUT